

Building Permit & Inspection Records

Building Permit and Inspection Records

Disclaimer

The information presented on this website is informational only and does not necessarily reflect the current condition of the building or property. The fact that a permit was issued does not confirm that work was performed, or that work was performed in accordance with that permit and the requirements of the Municipal Code.

Information on inspections and alleged violations reflect conditions found by the inspector at the time of the inspection and not necessarily the current status of those alleged violations or the current condition of the property. The absence of alleged violations on this website does not mean a building or property is in compliance with the requirements of the Municipal Code.

The Department of Buildings may refer certain alleged violations to the City's Department of Law for enforcement proceedings in the Department of Administrative Hearings or the Circuit Court of Cook County. Please contact the Department of Administrative Hearings or the Clerk of the Circuit Court, respectively to obtain records of these proceedings.

INPUT ADDRESS

1446 N DEARBORN ST

RANGE ADDRESS

1446-1446 N DEARBORN ST CHICAGO IL 60610

BUILDING ATTRIBUTES

BLDG ID	STORIES	BASEMENT	LENGTH	WIDTH	HEIGHT	FLR AREA	CONSTR TYPE	PORCH	LOT WIDTH	LOT LENGTH	DU
308838	5	Υ	96	45	0	4320	1A		45	96	26

BUILDING PERMITS

PERMIT #	DATE ISSUED	DESCRIPTION OF WORK
100840250	09/11/2019	Replacement of Power Unit on One(1) 2000LB Capacity, 5-Floor, Passenger, Hydraulic Elevator, pursuant to the scope of work submitted.(EV001515)
100777565	08/28/2018	SPRINT SWAPPING 3 LIKE ANTENNAS/RADIOS AT THE ANTENNA CH60XC148.
100777039	08/09/2018	UPGRADE TO EXISTING WIRELESS SYSTEM
100624570	11/23/2015	REINSTATE PERMIT # 100591123

PERMIT #	DATE ISSUED	DESCRIPTION OF WORK	
100591123	05/15/2015	MODIFYING THE EXISTING WIRELESS INSTALLATION: INSTALL (3) NEW 1900MHZ PANEL ANTENNAS; INSTALL (3) NEW 1900MHZ RRU(S); INSTALL (1) NEW 1900MHZ DU IN EXISTING MMBS; INSTALL (1) NEW GROWTH CABINET; INSTALL (2) NEW HYBRID CABLES AS PER PLANS SITE #: CH60XC148 PREVIOUS APP #: 100415137	
100591336	04/22/2015	MAINTENANCE TO EXISTING EQUIPMENT.	
100561863	09/23/2014	INSTALLATION OF NEW ANTENNAS ON EXISTING MOUNTS AND A NEW EQUIPMENT CABINET ON AND EXISTING STRUCTURAL PLATFORM AS PER PLANS. SITE # CH60XC148. PREVIOUS PERMIT# 100415137	
100560834	09/18/2014	UPGRADE OF EXISTING CARRIER EQUIPMENT	
100415137	02/16/2012	ADD 6 NEW ANTENNAS ON NEW SLED MOUNTS WITH RELATED ELECTRICAL EQUIPMENT ON AN EXISTING ROOFTOP WIRELESS COMMUNICATIONS FACILITY AS PER PLANS. CH60XC148	
100357644	08/09/2010	INSTALL 3 WATERPROOF LIGHTS ON THE OUTSIDE OF THE BUILDING.	
100020405	12/06/2004	NEW ANTENNAS ON EXISTING ROOFTOP AS PER PLAN	
B20418881	12/06/2004	NEW ANTENNAS ON EXISTING ROOFTOP AS PER PLAN	
B20025269	11/08/2000	REPLACEMENT OF THE HYDRAULIC CYLINDER.	
B97039022	07/14/1997	INSTALLATION OF DOOR RESTRICTOR ONE (1) PASS ADAMS HATCH LATCH	
EL9270485	07/14/1993	LOW VOLTAGE RESIDEN-TIAL BURGLAR ALARM	
EL7323796	02/11/1987	-	
EL7294183	01/06/1987	PERMIT REPAIRS	
EL5587908	10/20/1981	1017A CHANGE METER FITTING FOR APT B,C	
EL5272780	10/02/1980	2 APRT WERE COMBINED W/1 ELECT METER APT	

BUILDING CODE ENFORCEMENT CASE ACTIVITY

CASE NUMBER	CASE TYPE
12CO328398	ADMINISTRATIVE HEARING
10C0244344	ADMINISTRATIVE HEARING
09LO206931	ADMINISTRATIVE HEARING
09CO205779	ADMINISTRATIVE HEARING

DEPARTMENT OF BUILDINGS INSPECTIONS

INSP#	INSPECTION DATE	STATUS	TYPE DESCRIPTION
13011143	10/11/2019	PASSED	PERMIT INSPECTION
12659265	02/21/2019	PASSED	ELECTRICAL PERMIT INSPECTION
11331899	11/24/2014	PASSED	ELECTRICAL PERMIT INSPECTION
11366938	11/24/2014	PASSED	ELECTRICAL PERMIT INSPECTION
10238515	03/01/2012	FAILED	CONSERVATION ANNUAL
9987584	03/03/2011	FAILED	CONSERVATION ANNUAL
2678310	08/24/2010	FAILED	CONSERVATION ANNUAL
9759953	05/18/2010	FAILED	ANNUAL INSPECTION
2850749	12/30/2009	FAILED	CONSERVATION COMPLAINT INSPECT
2689651	03/23/2009	FAILED	ELECTRIC COMPLAINT INSPECTION
2346750	01/30/2009	FAILED	CONSERVATION ANNUAL
2171573	08/06/2008	FAILED	CONSERVATION ANNUAL
9550707	08/11/1999	CLOSED	ELEVATOR LEGACY INSPECTION
9514158	09/22/1998	CLOSED	ELEVATOR LEGACY INSPECTION

ALLEGED CODE VIOLATIONS

	CONSERVATION ANNUAL # 9987584 INSPECTION DATE: 03/03/2011	Number of Violations: 10
VIOLATIONS	BUILDING CODE CITATION	VIOLATION DETAILS
CN031013	Failed to install approved fire extinguishers on every floor of residential building more than three stories in height and having floor area exceeding 3,000 square feet. (15-16-160, 15-16-640)	FIRE EXTINGUISHERS - SOME AREA'S MISSING IN STAIRWAYS - 4 WEST, 2 WEST, 2 EAST
CN031013	Failed to install approved fire extinguishers on every floor of residential building more than three stories in height and having floor area exceeding 3,000 square feet. (15-16-160, 15-16-640)	Interior corridors/ stairs missing fire exstinguishers.
CN031023	Failed to maintain properly charged fire extinguisher and to attach tag which clearly indicates recharge date and signature of the person who performed the recharge. (15-16-680)	Intrerior corridors/ stairs the few fire exsinguishers installed exspired,not charged and missing tags.

CN031023	Failed to maintain properly charged fire extinguisher and to attach tag which clearly indicates recharge date and signature of the person who performed the recharge. (15-16-680)	FIRE EXTINGUISHERS THRU-OUT MISSING TAGS
CN061014	Failed to maintain the exterior walls of a building or structure free from holes, breaks, loose or rotting boards or timbers and any other conditions which might admit rain or dampness to the walls. (13-196-530(b), 13-196-641)	REAR AT GRADE EXTERIOR PARKING AREA - MISSING AND LOOSE TILES
CN066034	Failed to maintain balcony in good repair and free from cracks and defects. (13-196-530(e), 13-196-641)	SPALLING CEMENT UNDER 5TH FLOOR BALCONIES, EXPOSED REBARS front and rear.
CN067014	Failed to maintain roof in sound condition and repair, watertight and free from defects. (13-196-530, 13-196-530(c) and 13-196-641)	5TH FLOOR WEST ROOF HATCH IS MISSING
CN101015	Failed to maintain interior walls and ceilings free from holes or cracks. (13-19-540(c))	FIFTH FLOOR CORRIDOR CEILING HAS WATER DAMAGED AREA - BLISTERING PAINT - ALSO 2ND FLOOR CORRIDOR WALLS AND CEILINGS.
CN105035	Repair or replace door hardware. (13-196-550)	INTERIOR STAIRWAY 4 EAST BROKEN HINGES ON DOOR
EL0027	Restore exit and emergency lighting system and related equipment to operable condition. (18-27-700.6)	EMERGENCY BACKUP BATTERY LIGHTING - BATTERIES DEAD
	CONSERVATION ANNUAL # 2678310 INSPECTION DATE: 08/24/2010	Number of Violations: 10
VIOLATIONS	BUILDING CODE CITATION	VIOLATION DETAILS
CN061014	Failed to maintain the exterior walls of a building or structure free from holes, breaks, loose or rotting boards or timbers and any other conditions which might admit rain or dampness to the walls. (13-196-530(b), 13-196-641)	REAR AT GRADE EXTERIOR PARKING AREA - MISSING AND LOOSE TILES
CN062024	Failed to maintain parapet wall in good repair and free from cracks and defects. (13-196-530 and 13-196-641)	rear parapet wall washout mortar
CN066034	Failed to maintain balcony in good repair and free from cracks and defects. (13-196-530(e), 13-196-641)	SPALLING CEMENT UNDER 5TH FLOOR BALCONIES, EXPOSED REBARS
CN067014	Failed to maintain roof in sound condition and repair, watertight and free from defects. (13-196-530, 13-196-530(c) and 13-196-641)	5TH FLOOR WEST ROOF HATCH IS MISSING
CN101015	Failed to maintain interior walls and ceilings free from holes or cracks. (13-19-540(c))	FIFTH FLOOR CORRIDOR CEILING HAS WATER DAMAGED AREA - BLISTERING PAINT - ALSO 2ND FLOOR CORRIDOR WALLS AND CEILINGS.

CN105015	Repair or replace defective door. (13-196-550)	2ND EAST STAIRWELL DOOR - RESET DOOR - RUBS/JAMS
CN105035	Repair or replace door hardware. (13-196-550)	INTERIOR STAIRWAY 4 EAST BROKEN HINGES ON DOOR
CN132046	Provide and maintain every facility, piece of equipment, or utility in safe and sound working condition. (13-196-400, 13-196-440)	INTERIOR STAIRWAYS AND CORRIDORS - LOOSE AN HANGING BASEBOARD HEATERS ALSO NO HEAT PROVIDED
CN190029	pending notice reinspection	unable to verify complaint sr100925102,detectors,occupancy,and condition thru-out,unable to complete annual inspection
PL237058	Provide discharge pipe from water heater and hot water storage tank relief valve. (18-29-504.7.1)	LAUNDRY ROOM AT GRADE - HOT WATER TANK PRESSURE RELIEF VALVE IS MISSING PIPE TO GROUND
	ANNUAL INSPECTION # 9759953 INSPECTION DATE: 05/18/2010	Number of Violations: 5
VIOLATIONS	BUILDING CODE CITATION	VIOLATION DETAILS
199029		Perform Category I test as required by Code. (Chapter 18-30 of The City of Chicago Building Code and ASME 17.1 2007)
199029		Level of elevator sporatic. Adjust valve.
199029		Car door restrictor rendered in operative.
199029		Certificate frame in elevator cab Chgo 1(13-20-110).
199029		Capacity plate in elevator cab.
	CONSERVATION ANNUAL # 2346750 INSPECTION DATE: 01/30/2009	Number of Violations: 5
VIOLATIONS	BUILDING CODE CITATION	VIOLATION DETAILS
CN031013	Failed to install approved fire extinguishers on every floor of residential building more than three stories in height and having floor area exceeding 3,000 square feet. (15-16-160, 15-16-640)	FIRE EXTINGUISHERS - SOME AREA'S MISSING IN STAIRWAYS - 4 WEST, 2 WEST, 2 EAST
CN031023	Failed to maintain properly charged fire extinguisher	FIRE EXTINGUISHERS THRU-OUT MISSING TAGS

CN061014	Failed to maintain the exterior walls of a building or structure free from holes, breaks, loose or rotting boards or timbers and any other conditions which might admit rain or dampness to the walls. (13-196-530(b), 13-196-641)	REAR AT GRADE EXTERIOR PARKING AREA - MISSING AND LOOSE TILES
CN066034	Failed to maintain balcony in good repair and free from cracks and defects. (13-196-530(e), 13-196-641)	SPALLING CEMENT UNDER 5TH FLOOR BALCONIES, EXPOSED REBARS
EL0027	Restore exit and emergency lighting system and related equipment to operable condition. (18-27-700.6)	EMERGENCY BACKUP BATTERY LIGHTING - BATTERIES DEAD
	CONSERVATION ANNUAL # 2171573 INSPECTION DATE: 08/06/2008	Number of Violations: 2
VIOLATIONS	BUILDING CODE CITATION	VIOLATION DETAILS
CN066034	Failed to maintain balcony in good repair and free from cracks and defects. (13-196-530(e), 13-196-641)	SPALLING CEMENT UNDER 5TH FLOOR BALCONIES, EXPOSED REBARS
CN190019	Arrange for inspection of premises. (13-12-100)	NO ENTRY FOR ANNUAL INSPECTIONS
	CONSERVATION COMPLAINT INSPECT # 2850749 INSPECTION DATE: 12/30/2009	Number of Violations: 4
VIOLATIONS	BUILDING CODE CITATION	VIOLATION DETAILS
CN031013	Failed to install approved fire extinguishers on every floor of residential building more than three stories in height and having floor area exceeding 3,000 square feet. (15-16-160, 15-16-640)	Without fire extinguishers
CN031023	Failed to maintain properly charged fire extinguisher and to attach tag which clearly indicates recharge date and signature of the person who performed the recharge. (15-16-680)	Charge and tag extinguishers
CN061014	Failed to maintain the exterior walls of a building or structure free from holes, breaks, loose or rotting boards or timbers and any other conditions which might admit rain or dampness to the walls. (13-196-530(b), 13-196-641)	Exterior grid ceiling over parking garage loose and sagging sections.
CN066034	Failed to maintain balcony in good repair and free from cracks and defects. (13-196-530(e), 13-196-641)	Spalling concrete at underneath balconies all levels also exposed rebar.

Home: Disclaimer: Privacy Policy: Web Standards: Site Credits: Site Map: Contact Us: Press Room

Copyright © 2018 - 2020 City of Chicago