



Building Permit and Inspection Records

Disclaimer

The information presented on this website is informational only and does not necessarily reflect the current condition of the building or property. The fact that a permit was issued does not confirm that work was performed, or that work was performed in accordance with that permit and the requirements of the Municipal Code.

Information on inspections and alleged violations reflect conditions found by the inspector at the time of the inspection and not necessarily the current status of those alleged violations or the current condition of the property. The absence of alleged violations on this website does not mean a building or property is in compliance with the requirements of the Municipal Code.

The Department of Buildings may refer certain alleged violations to the City's Department of Law for enforcement proceedings in the Department of Administrative Hearings or the Circuit Court of Cook County. Please contact the [Department of Administrative Hearings](#) or the [Clerk of the Circuit Court](#), respectively to obtain records of these proceedings.

INPUT ADDRESS

947 W CORNELIA AVE

RANGE ADDRESS

3445-3459 N SHEFFIELD AVE CHICAGO IL 60657

947-957 W CORNELIA AVE CHICAGO IL 60657

BUILDING ATTRIBUTES

BLDG ID	STORIES	BASEMENT	LENGTH	WIDTH	HEIGHT	FLR AREA	CONSTR TYPE	PORCH	LOT WIDTH	LOT LENGTH	DU
185335	4	Y	150	125	0	18750	3B		125	150	62

BUILDING PERMITS

PERMIT #	DATE ISSUED	DESCRIPTION OF WORK
100666342	08/24/2016	INSTALL NEW ELECTRICAL METER AND SEPARATE POWER FOR UNITS 955 -1C AND 949 - 3D
100637990	03/03/2016	SEPARATE CIRCUITS AND INSTALL 2 NEW METERS AND PANELS FOR 2 NEW UNITS 3A AND 2D
100545801	06/17/2014	INSTALL NEW 2400 AMP SERVICE WITH 61 NEW METERS
100524508	01/19/2014	INSTALL NEW ELECTRIC BASEBOARD FOR 60 UNITS.
100190624	08/01/2007	REPAIR 3 EXISTING PORCHES AND STAIRS AS PER PLANS.

PERMIT #	DATE ISSUED	DESCRIPTION OF WORK
B20409395	04/30/2004	REPAIR INSIDE STAIRS ALL WORK SAME AS EXISTING
B20300653	01/10/2003	REMOVE AND REPAIR THE WINDOWS SAME IN SIZES AS EXISTING
B20228152	11/04/2002	MASONARY, LINTELS, TUCKPOINTING, WASHING AS NEEDED
EL6385293	05/14/1984	REPLACE DAMAGE SERV CONDUIT TO REANCHOR

DEPARTMENT OF BUILDINGS INSPECTIONS

INSP #	INSPECTION DATE	STATUS	TYPE DESCRIPTION
12693133	10/05/2018	FAILED	CONSERVATION COMPLAINT INSPECT
12555974	02/02/2018	FAILED	CONSERVATION COMPLAINT INSPECT
11680511	10/13/2015	FAILED	CONSERVATION COMPLAINT INSPECT
11443797	05/29/2015	FAILED	CONSERVATION ANNUAL
11264406	07/16/2014	PASSED	ELECTRICAL PERMIT INSPECTION
11083053	07/16/2014	PASSED	ELECTRICAL PERMIT INSPECTION
1952293	07/27/2009	CLOSED	PORCH/DECK PERMIT INSPECTION
2503477	05/18/2009	PASSED	BOILER ANNUAL INSPECTION
2067083	02/21/2008	PASSED	BOILER ANNUAL INSPECTION
1952292	09/04/2007	PASSED	DOB NEW CONSTRUCTION INSP
1644915	01/02/2007	PASSED	BOILER ANNUAL INSPECTION
1426186	04/25/2006	PASSED	CONSERVATION ANNUAL
943390	10/13/2005	PASSED	BOILER ANNUAL INSPECTION
570661	10/04/2004	PASSED	BOILER ANNUAL INSPECTION
430580	06/09/2003	PASSED	BOILER ANNUAL INSPECTION
159724	06/13/2002	PASSED	BOILER ANNUAL INSPECTION

ALLEGED CODE VIOLATIONS

--	--	--

	CONSERVATION COMPLAINT INSPECT # 12693133 INSPECTION DATE: 10/05/2018	Number of Violations: 2
VIOLATIONS	BUILDING CODE CITATION	VIOLATION DETAILS
CN070014	Failed to maintain exterior stairways in safe condition and in sound repair. (13-196-570, 13-196-641)	3449-51 exterior concrete entry stairs-cracked and missing section of tread and riser.
CN190019	Arrange for inspection of premises. (13-12-100)	Building / no entry,unverified detectors,conditions,unable to verify complaint of 3449 basement apartment-rats inside walls.
	CONSERVATION COMPLAINT INSPECT # 12555974 INSPECTION DATE: 02/02/2018	Number of Violations: 1
VIOLATIONS	BUILDING CODE CITATION	VIOLATION DETAILS
CN190019	Arrange for inspection of premises. (13-12-100)	No response; no entry. Unable to inspect interior, stairwells, apartments, basement, rear premises, and rear porches. Unverified detectors and conditions.
	CONSERVATION COMPLAINT INSPECT # 11680511 INSPECTION DATE: 10/13/2015	Number of Violations: 1
VIOLATIONS	BUILDING CODE CITATION	VIOLATION DETAILS
CN190019	Arrange for inspection of premises. (13-12-100)	Interior of the building - no response, unverified detectors and conditions. Rear yard - locked gates, unable to inspect rear porches.

[Home](#) : [Disclaimer](#) : [Privacy Policy](#) : [Web Standards](#) : [Site Credits](#) : [Site Map](#) : [Contact Us](#) : [Press Room](#)

Copyright © 2018 - 2020 City of Chicago